



Biological Monitoring
Service Provider

And Our Partner



STERILIZER TEST RESULTS

Avant-Garde
7219 W GREENFIELD AVE
MILWAUKEE, WI 53214
Phone: (414) 607-4068
Fax: (414) 607-0600
Customer ID: AD521

Print Date: 6/15/2016

RESULT:

PASS

Test No: BQ93329

Operator:

CURRENT TEST	
TEST DATE	5/15/2016
RECEIVED	5/26/2016
FINAL RESULT	5/27/2016
BRAND	Midmark
MODEL	M9
STERILIZER ID	V1627851
STERILIZER TYPE	Steam
RESULT	Passed. No growth observed after incubation period.

PREVIOUS TEST	
TEST DATE	4/15/2016
RECEIVED	4/25/2016
FINAL RESULT	4/26/2016
BRAND	Midmark
MODEL	M9
STERILIZER ID	V1627851
STERILIZER TYPE	Steam
RESULT	Passed. No growth observed after incubation period.

Reminder: In addition to conducting routine biological monitoring as recommended by the CDC, equipment users should perform biological monitoring for the following occurrences:

- ✓ Whenever a new type of packaging material tray/cassette is used.
- ✓ After training new sterilization personnel.
- ✓ After a sterilizer has been serviced/repared.
- ✓ After any change in the sterilization loading or processing procedures.
- ✓ During initial use of a new sterilizer.

Sincerely,

A handwritten signature in black ink that reads "Leann Keefer, RDH, MSM". The signature is written in a cursive style.

Leann Keefer, RDH, MSM
General Manager

Crosstex BMS
109 Inverness Drive East, Unit F
Englewood, Colorado 80112-5105
Toll Free: 1-800-819-3336
T: 303-699-3356 | F: 303-699-8255
E: customercare@crosstex.com
CrosstexBMS.com